

# Division of Maintenance



8301 Turkey Thicket Drive, Building A, First Floor  
Gaithersburg, MD 20879  
(240) 740-2500

Attachment A

## MONTGOMERY COUNTY PUBLIC SCHOOLS ANNUAL NOTIFICATION OF ASBESTOS MANAGEMENT PLAN AVAILABILITY

In 1987, the U.S. Environmental Protection Agency (EPA) issued the final regulations for the Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763. These regulations require local education agencies to prepare Asbestos Management Plans for facilities that have asbestos containing materials (ACM). An Asbestos Management Plan must contain the following elements:

- Results of surveys and assessments of ACM in the facility, performed by certified inspection personnel;
- A detailed plan for managing ACM in the facility and time frames for removal, if applicable;
- A program for operations and maintenance activities to avoid accidental disturbance of ACM during routine maintenance and for abatement services as required;
- A program for periodic surveillance of ACM and an emergency response action plan to address unanticipated problems; and
- Provisions for centralized coordination of all aspects of the asbestos program.

This notification is being provided to comply with the public notification requirement of AHERA. The Asbestos Management Plan and the most recent inspection report for your school are available at the main office for review.

It is important to note that both the EPA and the Maryland State Department of the Environment have indicated that the presence of ACM in buildings does not in itself constitute a health hazard. If the material is not damaged or disturbed, it is not a danger to workers or other occupants. The Montgomery County Public Schools Asbestos Management Program is designed to ensure that any ACM remain in good condition until removed during a major renovation or revitalization/expansion project.

If you have questions, please contact Mr. John Conaway, environmental health specialist, Environmental Services/Indoor Air Quality Unit, Division of Maintenance, at 240-740-2331 or [John\\_D\\_Conaway@mcpsmd.org](mailto:John_D_Conaway@mcpsmd.org).

# Division of Maintenance



8301 Turkey Thicket Drive, Building A, First Floor  
Gaithersburg, MD 20879  
(240) 740-2500

Attachment B

## MONTGOMERY COUNTY PUBLIC SCHOOLS NOTIFICACIÓN ANUAL DE LA DISPONIBILIDAD DEL PLAN DE CONTROL DE ASBESTO

En 1987, la Agencia de Protección Ambiental (Environmental Protection Agency -EPA) publicó las normas definitivas para Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763. Estas normas exigen que las Agencias Educativas Locales (Local Education Agencies-LEAs) preparen Planes de Gestión de Asbesto para los edificios que tengan materiales que contengan asbesto (ACM). Un Plan de Gestión de Asbesto debe contener los siguientes elementos:

- Los resultados de encuestas y evaluaciones de ACM de la instalación, realizados por personal de inspección certificado.
- Un plan detallado para administrar ACM en el edificio y un plan cronológico para la eliminación, si es necesario.
- Un programa de actividades para las operaciones y mantenimiento para evitar disturbios accidentales de ACM durante los servicios rutinarios de mantenimiento y disminución requeridos.
- Un programa para vigilancia periódica de ACM y un plan de acción en caso de emergencia para responder a problemas no anticipados.
- Planes para una coordinación centralizada de todos los aspectos del programa de asbesto.

Esta notificación está siendo suministrada para cumplir con el requisito de notificación pública de AHERA. El plan de control de asbesto y el más reciente informe de inspección de su escuela está disponible en la oficina principal para revisión.

Es importante destacar que tanto EPA como Maryland State Department of the Environment (MDE) han indicado que la presencia de materiales ACM en las instalaciones no constituye, en sí, un peligro a la salud. Si el material no es dañado o perturbado, los trabajadores u otros ocupantes del edificio no corren peligro. MCPS Asbestos Management Program está diseñado para asegurar que cualquier material que contenga ACM permanezca en buenas condiciones hasta que sea retirado durante una renovación o proyecto de revitalización/expansión.

Si tiene preguntas, comuníquese con el Sr. John Conaway, Especialista en Salud Ambiental, Environmental Services/Indoor Air Quality Unit, Division of Maintenance, al 240-740-2331 o [John\\_D\\_Conaway@mcps.org](mailto:John_D_Conaway@mcps.org).